

CAUTION: DISCONNECT ELECTRIC CURRENT BEFORE SERVICING. LABEL ALL WIRES PRIOR TO DISCONNECTION WHEN SERVICING CONTROLS. WIRING ERRORS CAN CAUSE IMPROPER AND DANGEROUS OPERATION. VERIFY PROPER OPERATION AFTER SERVICING.

CIRCUIT	TERM	WIRING	REGULAR			OFF	EX. RINSE	OFF	PERM. PRESS			OFF	KNITS & DELICATE			OFF	SOAK			OFF
			WASH (15 MIN)	PUMP (6 MIN)	PUMP (12 MIN)		PUMP (9 MIN)		WASH (12 MIN)	PUMP (6 MIN)	PUMP (6 MIN)		WASH (6 MIN)	PUMP (6 MIN)	PUMP (6 MIN)		SOAK (12 MIN)	PUMP (6 MIN)		
0	2	1	T	WATER TEMP																
0	2	3	B	SES SPRAY																
2	5	4	T	WASH FILL																
2	5	6	B	RINSE FILL																
4	8	7	T	LID SW BYPASS																
4	8	9	B	PUMP																
6	11	10	T	SPIN DR																
6	11	12	B	AGITATE DR																
6	11	13	T	AGITATE DR																
8	14	14	B	SPIN DR																
10	17	16	T	ADV EX RINSE																
10	17	18	B	ADV SOAK																
12	20	19	T	P.S. BYPASS																
12	20	21	B	HIGH SPEED MOTOR																
14	23	22	T	P.S. BYPASS																
14	23	24	B	LOW SPEED MOTOR																

